

Ship Name: **BBC CENTURY**
Ship Type: **General Dry Cargo Ship**
Flag: **Antigua and Barbuda**
IMO Number: **9253260**
Date of Action: **7/28/2020**
Action Taken: **Detention**
Port: **Baltimore, Maryland**
Unit: **Sector Maryland-NCR**

Recognized Org: **Nippon Kaiji Kyokai**
Recognized Security Organization (RSO):
Recognized Org (RO) Related: **Not Class Related**
Relevant Certificates:
Organization Related to Detention:
Ship Management: Owners, Operators, or Managers
Jungerhans Heavy-Lift-Fleet Services GmbH & Co. KG
MS "Luna J" Schiffahrtsgesellschaft
Charterers
BBC Chartering & Logistic GmbH & Co KG

Deficiencies: Code - Category

15110 - Documentation-ISM

Description

The company should ensure any non-conformity is reported with its possible cause, if known. PSCO observed hydraulic oil pooled on and under the steering gear due to hydraulic oil leak. The vessel's planned/preventive maintenance listed the steering gear as "ok". PSCO observed non-reflective retroreflective tape on the lifeboat and rescue boat as well as wasted gasket on the lifeboat door. The vessel's planned/preventative maintenance for the lifeboat and rescue boat were "all in satisfactory condition."

07126 - Oil accumulation in engine room

The condition of the ship and its equipment shall be maintained to conform with the provisions of the present convention. PSCOs observed pooled oil throughout the engine room to include below and on top of the main engine, under the HFO purifier, under the air compressors and next to the boiler. Fuel oil was also leaking from the MDO pipeline next to the OWS.

14104 - Oil filtering equipment

The condition of the ship and its equipment shall be maintained to conform with the provisions of the present convention. The vessel's crew failed to properly operate the oily water separator.

